

## إعادة تأهيل ابار النفط والغاز



Oil wells in the fields were subject to acts of sabotage through the bombing and bombing of the well heads and the oil flowed from some of them freely.

The following works were carried out by the technical team of our company:

1. Control of wells in which oil and stratified water flow.
2. Drilling and detection of damaged parts of the casing pipes and the wellhead.
3. Cutting the damaged packaging pipes and replacing them with new ones, along with centering and re-installing the Christmas tree.
4. Reinforcing the casing with cement and re-equipping the sealer to its initial position.


# إعادة تأهيل ابار النفط والغاز

Detecting damaged casing from an oil well to be replaced



## إعادة تأهيل ابار النفط والغاز

Cut the damaged parts of the casing pipes to be replaced with new.



# إعادة تأهيل ابار النفط والغاز

the oil well after replacing the damaged casing with new ones



# إعادة تأهيل ابار النفط والغاز

Installation of the well head, Christmas tree and preparation for cementing

